


| | |
|------------|----------------|
| Car Number | Chassis Number |
| F24-I96 | NHW20-0085319 |



(Remark)
Right side power mirror isn't working

A(Scratch) U(Dent) S(Rust) W(Uneven paint) X(Crack) C(Corrode) P(Paint Faded)
 XX(Replacement) X(Replacement requires) G(Stone chip in the glass) Scale: 1 < 2 < 3 < 4