


Car Number	Chassis Number
F11-C82	AVU65-0027861



(Remark)

**A(Scratch)**    **U(Dent)**    **S(Rust)**    **W(Uneven paint)**    **X(Crack)**    **C(Corrode)**    **P(Paint Faded)**  
**XX(Replacement)**    **X(Replacement requires)**    **G(Stone chip in the glass)**    **Scale: 1 < 2 < 3 < 4**