


DATE
2024/8/20

Car Number	Chassis Number
F06-H08	ZVW30-5500674



(Remark)  
Navigation screen is broken

A(Scratch)    U(Dent)    S(Rust)    W(Uneven paint)    X(Crack)    C(Corrode)    P(Paint Faded)  
 XX(Replacement)    X(Replacement requires)    G(Stone chip in the glass)    Scale: 1 < 2 < 3 < 4