


DATE
2024/4/27

Car Number	Chassis Number
F10-D76	NHP160-0005296



(Remark)
 There is a tear in the driver's sheet

A(Scratch) **U**(Dent) **S**(Rust) **W**(Uneven paint) **X**(Crack) **C**(Corrode) **P**(Paint Faded)
XX(Replacement) **X**(Replacement requires) **G**(Stone chip in the glass) **Scale: 1 < 2 < 3 < 4**