


DATE
2024/9/10

Car Number	Chassis Number
F14-H54	GRX130-6072217



(Remark)

A (Scratch) U (Dent) S (Rust) W (Uneven paint) X (Crack) C (Corrode) P (Paint Faded)
 XX (Replacement) X (Replacement requires) G (Stone chip in the glass) Scale: 1 < 2 < 3 < 4