


Car Number	Chassis Number
F20-H78	ZVW41-0083663



(Remark)  
Smoking smell and cigarette marks on the ceiling and the sheet

A(Scratch)    U(Dent)    S(Rust)    W(Uneven paint)    X(Crack)    C(Corrode)    P(Paint Faded)

XX(Replacement)    X(Replacement requires)    G(Stone chip in the glass)    Scale: 1 < 2 < 3 < 4