


| | |
|------------|----------------|
| Car Number | Chassis Number |
| F20-K47 | ZRR70-0294933 |



(Remark)
Left side power mirror isn't working