


DATE
2024/9/14

Car Number	Chassis Number
F21-H97	GRS182-1046492



(Remark)
Crack on the dashboard

A(Scratch) U(Dent) S(Rust) W(Uneven paint) X(Crack) C(Corrode) P(Paint Faded)
 XX(Replacement) X(Replacement requires) G(Stone chip in the glass) Scale: 1 < 2 < 3 < 4