


|            |                |
|------------|----------------|
| Car Number | Chassis Number |
| F22-H79    | ZVW50-6051079  |



(Remark)  
ITS©

A(Scratch)    U(Dent)    S(Rust)    W(Uneven paint)    X(Crack)    C(Corrode)    P(Paint Faded)  
 XX(Replacement)    X(Replacement requires)    G(Stone chip in the glass)    Scale: 1 < 2 < 3 < 4