


Car Number	Chassis Number
F22-L42	NZE141-9183104



(Remark)
Ripped driver's seat

A(Scratch) U(Dent) S(Rust) W(Uneven paint) X(Crack) C(Corrode) P(Paint Faded)
 XX(Replacement) X(Replacement requires) G(Stone chip in the glass) Scale: 1 < 2 < 3 < 4