


Car Number	Chassis Number
F23-H28	J200E-0025861



(Remark)  
The angle of both side power mirrors can not be changed

A(Scratch)    U(Dent)    S(Rust)    W(Uneven paint)    X(Crack)    C(Corrode)    P(Paint Faded)  
 XX(Replacement)    X(Replacement requires)    G(Stone chip in the glass)    Scale: 1 < 2 < 3 < 4