




DATE _____

2025/5/9

Car Number	Chassis Number
G02-D85	GK3-1035653



(Remark)

A(Scratch)

U (Dent)

S (Rust)

W (Uneven paint)

X(Crack)

C (Corrode)

P (Paint Faded)

XX (Replacement)

X(Replacement requires)

G(Stone chip in the glass)

Scale: 1 < 2 < 3 < 4