


Car Number

Chassis Number

G05-D89

AZK10-2087254



(Remark)

A(Scratch)

U(Dent)

S(Rust)

W(Uneven paint)

X(Crack)

C(Corrode)

P(Paint Faded)

XX(Replacement)

X(Replacement requires)

G(Stone chip in the glass)

Scale: 1 &lt; 2 &lt; 3 &lt; 4