


Car Number	Chassis Number
G07-B60	NHP10-2501863



(Remark)
Smoking smell / Unclear side windows due to the UV protect spray

A(Scratch) U(Dent) S(Rust) W(Uneven paint) X(Crack) C(Corrode) P(Paint Faded)
 XX(Replacement) X(Replacement requires) G(Stone chip in the glass) Scale: 1 < 2 < 3 < 4