



DATE


2025/4/25

Car Number

Chassis Number

G09-D58

NRE214-0001316



(Remark)

A (Scratch)

U (Dent)

S (Rust)

W (Uneven paint)

X (Crack)

C (Corrode)

P (Paint Faded)

XX (Replacement)

X (Replacement requires)

G (Stone chip in the glass)

Scale: 1 < 2 < 3 < 4