


DATE
2025/2/19

Car Number	Chassis Number
G11-A86	ZSU60-0110201



(Remark)
 Side member repair history
 Bonnet dumper X

A(Scratch) U(Dent) S(Rust) W(Uneven paint) X(Crack) C(Corrode) P(Paint Faded)
 XX(Replacement) X(Replacement requires) G(Stone chip in the glass) Scale: 1 < 2 < 3 < 4