


Car Number	Chassis Number
G18-A33	ZVW30-1950128



(Remark)  
 Color faded on the steering wheel  
 Missing driver side's floor mattress

A(Scratch)      U(Dent)      S(Rust)      W(Uneven paint)      X(Crack)      C(Corrode)      P(Paint Faded)  
 XX(Replacement)      X(Replacement requires)      G(Stone chip in the glass)      Scale: 1 < 2 < 3 < 4