


Car Number	Chassis Number
G20-C17	ZVW51-6146241



(Remark)

A(Scratch) **U**(Dent) **S**(Rust) **W**(Uneven paint) **X**(Crack) **C**(Corrode) **P**(Paint Faded)
XX(Replacement) **X**(Replacement requires) **G**(Stone chip in the glass) Scale: 1 < 2 < 3 < 4