

Car Number	Chassis Number
G25-E60	NSP130-2115204
The diagram is a top-down view of a vehicle chassis. At the top is a horizontal bar labeled 'P3'. Below it is a trapezoidal shape labeled 'P2'. In the center is a rectangular shape labeled 'G'. Below 'G' is another rectangular shape labeled 'P2'. At the bottom is a horizontal bar labeled 'A1'. On the left and right sides are vertical rectangular bars. On the left side, from top to bottom, are labels 'A1', 'U1', and 'A2'. On the right side, from top to bottom, are labels 'A2', 'A2', and 'A1 U1'. Two circular components are labeled 'Mirror P' with arrows pointing to them. A single circular component is shown at the bottom left.	
(Remark)	

A (Scratch)	U (Dent)	S (Rust)	W (Uneven paint)	X (Crack)	C (Corrode)	P (Paint Faded)
XX (Replacement)	X (Replacement requires)		G (Stone chip in the glass)		Scale: 1 < 2 < 3 < 4	