


Car Number

Chassis Number

G26-D27

GRX130-6022534



(Remark) Trunk floor W
Smells like cigarettes

A(Scratch)

U(Dent)

S(Rust)

W(Uneven paint)

X(Crack)

C(Corrode)

P(Paint Faded)

XX(Replacement)

X(Replacement requires)

G(Stone chip in the glass)

Scale: 1 < 2 < 3 < 4